



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **FR/LCI/QAR06.0006/21** Page 1 of 2

QAR Free Ref. No.: **23670639-804868 V00** Status: **Issued**

Details of change: Surveillance N°1 audit
Villars Sur Glâne, Switzerland Date of issue: **2025-03-06**

Location(s) audited: **Meggitt SA**
Route de Moncor 4
1752 Villars-sur-Glâne
Switzerland
Switzerland Valid until: **2027-01-27**

**TT Electronics Integrated Manufacturing Services
(Suzhou) Limited**
IMS 158-29 Hua Shan Road Feng Qiao Industrial Park
Suzhou New District Suzhou City Jiangsu Province
China Audit date: **2024-11-06**

Issuing ExCB: **LCIE - Laboratoire Central des Industries Electriques (LCIE)**

Manufacturer: **Meggitt SA**
Route de Moncor 4
1752 Villars-sur-Glâne
Switzerland

Location of
Manufacturer: **Switzerland**

Product information: Galvanic separation module
Signal charge conditionner
Accelerometer
Dynamic pressure sensor
Acceleration transducer

Type of protection: **EPL Ga : [ia], ia EPL Gb : [ib], ib, op pr, d EPL Db : tb EPL Gc : ec, nA, nC**

Related QARs:

FR/LCI/QAR06.0006/00
FR/LCI/QAR06.0006/03
FR/LCI/QAR06.0006/06
FR/LCI/QAR06.0006/09
FR/LCI/QAR06.0006/12
FR/LCI/QAR06.0006/15
FR/LCI/QAR06.0006/18

FR/LCI/QAR06.0006/01
FR/LCI/QAR06.0006/04
FR/LCI/QAR06.0006/07
FR/LCI/QAR06.0006/10
FR/LCI/QAR06.0006/13
FR/LCI/QAR06.0006/16
FR/LCI/QAR06.0006/19

FR/LCI/QAR06.0006/02
FR/LCI/QAR06.0006/05
FR/LCI/QAR06.0006/08
FR/LCI/QAR06.0006/11
FR/LCI/QAR06.0006/14
FR/LCI/QAR06.0006/17
FR/LCI/QAR06.0006/20

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

IECEx BAS 16.0030X issue: 0
IECEx CSAE 22.0047X issue: 0
IECEx EPS 22.0034X issue: 1
IECEx LCI 06.0007X issue: 2
IECEx LCI 06.0008X issue: 1
IECEx LCI 06.0009X issue: 0
IECEx LCI 06.0009X issue: 3
IECEx LCI 06.0010X issue: 2

IECEx BAS 16.0030X issue: 1
IECEx DEK 15.0029 issue: 0
IECEx LCI 06.0007X issue: 0
IECEx LCI 06.0007X issue: 3
IECEx LCI 06.0008X issue: 2
IECEx LCI 06.0009X issue: 1
IECEx LCI 06.0010X issue: 0
IECEx LCI 06.0010X issue: 3

IECEx BAS 16.0030X issue: 2
IECEx DEK 23.0049X issue: 0
IECEx LCI 06.0007X issue: 1
IECEx LCI 06.0008X issue: 0
IECEx LCI 06.0008X issue: 3
IECEx LCI 06.0009X issue: 2
IECEx LCI 06.0010X issue: 1
IECEx LCI 08.0041X issue: 0

-- Continued on the next page



IECEX Quality Assessment Report Summary

QAR Ref. No.: **FR/LCI/QAR06.0006/21**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEX LCI 08.0041X issue: 1	IECEX LCI 08.0041X issue: 2	IECEX LCI 08.0041X issue: 3
IECEX LCI 08.0041X issue: 4	IECEX LCI 10.0002X issue: 0	IECEX LCI 10.0002X issue: 1
IECEX LCI 10.0002X issue: 2	IECEX LCI 10.0002X issue: 3	IECEX LCI 10.0007X issue: 0
IECEX LCI 10.0007X issue: 1	IECEX LCI 10.0007X issue: 2	IECEX LCI 10.0007X issue: 3
IECEX LCI 10.0007X issue: 4	IECEX LCI 10.0013X issue: 0	IECEX LCI 10.0013X issue: 1
IECEX LCI 10.0013X issue: 2	IECEX LCI 10.0014X issue: 0	IECEX LCI 10.0014X issue: 1
IECEX LCI 10.0014X issue: 2	IECEX LCI 10.0015X issue: 0	IECEX LCI 10.0015X issue: 1
IECEX LCI 10.0015X issue: 2	IECEX LCI 10.0016X issue: 0	IECEX LCI 10.0016X issue: 1
IECEX LCI 10.0016X issue: 2	IECEX LCI 10.0017X issue: 0	IECEX LCI 10.0017X issue: 1
IECEX LCI 10.0017X issue: 2	IECEX LCI 10.0018X issue: 0	IECEX LCI 10.0018X issue: 1
IECEX LCI 10.0018X issue: 2	IECEX LCI 10.0019X issue: 0	IECEX LCI 10.0019X issue: 1
IECEX LCI 10.0019X issue: 2	IECEX LCI 10.0020X issue: 0	IECEX LCI 10.0020X issue: 1
IECEX LCI 10.0020X issue: 2	IECEX LCI 10.0020X issue: 3	IECEX LCI 10.0021X issue: 0
IECEX LCI 10.0021X issue: 1	IECEX LCI 10.0021X issue: 2	IECEX LCI 10.0021X issue: 3
IECEX LCI 10.0027X issue: 0	IECEX LCI 10.0027X issue: 1	IECEX LCI 10.0027X issue: 2
IECEX LCI 11.0061X issue: 0	IECEX LCI 11.0061X issue: 1	IECEX LCI 11.0061X issue: 2
IECEX LCI 11.0063X issue: 0	IECEX LCI 11.0063X issue: 1	IECEX LCI 11.0066X issue: 0
IECEX LCI 11.0066X issue: 1	IECEX LCI 11.0066X issue: 2	IECEX LCI 11.0066X issue: 3
IECEX LCI 12.0009X issue: 0	IECEX LCI 12.0009X issue: 1	IECEX LCIE 13.0001X issue: 0
IECEX LCIE 13.0001X issue: 1	IECEX LCIE 13.0001X issue: 2	IECEX LCIE 13.0026X issue: 0
IECEX LCIE 13.0026X issue: 1	IECEX LCIE 13.0026X issue: 2	IECEX LCIE 13.0053X issue: 0
IECEX LCIE 13.0058X issue: 0	IECEX LCIE 13.0058X issue: 1	IECEX LCIE 13.0058X issue: 2
IECEX LCIE 14.0042X issue: 0	IECEX LCIE 14.0056X issue: 0	IECEX LCIE 14.0056X issue: 1
IECEX LCIE 14.0056X issue: 2	IECEX LCIE 14.0058X issue: 0	IECEX LCIE 15.0024X issue: 0
IECEX LCIE 16.0054X issue: 0	IECEX LCIE 18.0023X issue: 0	IECEX LCIE 18.0023X issue: 1
IECEX LCIE 20.0026X issue: 0	IECEX LCIE 21.0005X issue: 0	IECEX LCIE 21.0005X issue: 1
IECEX LCIE 21.0005X issue: 2	IECEX LCIE 21.0006X issue: 0	IECEX LCIE 21.0006X issue: 1
IECEX LCIE 21.0006X issue: 2	IECEX PTZ 17.0002X issue: 2	IECEX SIR 11.0018 issue: 0
IECEX SIR 11.0018 issue: 1		

Comments: Production Quality Assurance Notification under directive 2014/34/EU : LCIE 03 ATEX Q 8001