



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **FR/LCI/QAR06.0006/17** Page 1 of 2  
QAR Free Ref. No.: **12995801-773674 (MEGGITT Switzerland) and  
16001934-781660 (TT Electronics China)** Status: **Issued**  
Details of change: **Surveillance 2** Date of issue: **2022-11-28**  
Site(s) audited: **TT Electronics Integrated Manufacturing Services  
(Suzhou) Limited** Valid until: **2024-01-27**  
**IMS 158-29 Hua Shan Road Feng Qiao Industrial Park**  
**Suzhou New District Suzhou City Jiangsu Province**  
**China** Audit date: **2022-10-19**

**MEGGITT SA**  
Route de Moncor 4  
1752 Villars-sur-Glâne  
Switzerland

Issuing ExCB: **LCIE - Laboratoire Central des Industries Electriques (LCIE)**

Manufacturer: **Meggitt SA**  
Route de Moncor 4  
1752 Villars-sur-Glâne  
Switzerland

Location of  
Manufacturer: **Switzerland**

Product information: Galvanic separation module  
Signal charge conditionner  
Accelerometer  
Dynamic pressure sensor  
Acceleration transducer

Protection concept: **EPL Ga : [ia], ia EPL Gb : [ib], ib, op pr EPL Gc : ec, nA, nC**

Related QARs:

FR/LCI/QAR06.0006/00  
FR/LCI/QAR06.0006/03  
FR/LCI/QAR06.0006/06  
FR/LCI/QAR06.0006/09  
FR/LCI/QAR06.0006/12  
FR/LCI/QAR06.0006/15

FR/LCI/QAR06.0006/01  
FR/LCI/QAR06.0006/04  
FR/LCI/QAR06.0006/07  
FR/LCI/QAR06.0006/10  
FR/LCI/QAR06.0006/13  
FR/LCI/QAR06.0006/16

FR/LCI/QAR06.0006/02  
FR/LCI/QAR06.0006/05  
FR/LCI/QAR06.0006/08  
FR/LCI/QAR06.0006/11  
FR/LCI/QAR06.0006/14

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for  
previous versions:

IECEX BAS 16.0030X issue: 0  
IECEX LCI 06.0007X issue: 0  
IECEX LCI 06.0007X issue: 3  
IECEX LCI 06.0008X issue: 2  
IECEX LCI 06.0009X issue: 1  
IECEX LCI 06.0010X issue: 0  
IECEX LCI 06.0010X issue: 3  
IECEX LCI 08.0041X issue: 2  
IECEX LCI 10.0002X issue: 1  
IECEX LCI 10.0007X issue: 0

IECEX BAS 16.0030X issue: 1  
IECEX LCI 06.0007X issue: 1  
IECEX LCI 06.0008X issue: 0  
IECEX LCI 06.0008X issue: 3  
IECEX LCI 06.0009X issue: 2  
IECEX LCI 06.0010X issue: 1  
IECEX LCI 08.0041X issue: 0  
IECEX LCI 08.0041X issue: 3  
IECEX LCI 10.0002X issue: 2  
IECEX LCI 10.0007X issue: 1

IECEX DEK 15.0029 issue: 0  
IECEX LCI 06.0007X issue: 2  
IECEX LCI 06.0008X issue: 1  
IECEX LCI 06.0009X issue: 0  
IECEX LCI 06.0009X issue: 3  
IECEX LCI 06.0010X issue: 2  
IECEX LCI 08.0041X issue: 1  
IECEX LCI 10.0002X issue: 0  
IECEX LCI 10.0002X issue: 3  
IECEX LCI 10.0007X issue: 2

-- Continued on the next page



# IECEX Quality Assessment Report Summary

QAR Ref. No.: **FR/LCI/QAR06.0006/17**

Page 2 of 2

Related Certificates for  
previous versions (continued):

IECEX LCI 10.0007X issue: 3	IECEX LCI 10.0013X issue: 0	IECEX LCI 10.0013X issue: 1
IECEX LCI 10.0013X issue: 2	IECEX LCI 10.0014X issue: 0	IECEX LCI 10.0014X issue: 1
IECEX LCI 10.0014X issue: 2	IECEX LCI 10.0015X issue: 0	IECEX LCI 10.0015X issue: 1
IECEX LCI 10.0015X issue: 2	IECEX LCI 10.0016X issue: 0	IECEX LCI 10.0016X issue: 1
IECEX LCI 10.0016X issue: 2	IECEX LCI 10.0017X issue: 0	IECEX LCI 10.0017X issue: 1
IECEX LCI 10.0017X issue: 2	IECEX LCI 10.0018X issue: 0	IECEX LCI 10.0018X issue: 1
IECEX LCI 10.0018X issue: 2	IECEX LCI 10.0019X issue: 0	IECEX LCI 10.0019X issue: 1
IECEX LCI 10.0019X issue: 2	IECEX LCI 10.0020X issue: 0	IECEX LCI 10.0020X issue: 1
IECEX LCI 10.0020X issue: 2	IECEX LCI 10.0021X issue: 0	IECEX LCI 10.0021X issue: 1
IECEX LCI 10.0021X issue: 2	IECEX LCI 10.0021X issue: 3	IECEX LCI 10.0027X issue: 0
IECEX LCI 10.0027X issue: 1	IECEX LCI 10.0027X issue: 2	IECEX LCI 10.0034X issue: 0
IECEX LCI 11.0061X issue: 0	IECEX LCI 11.0061X issue: 1	IECEX LCI 11.0061X issue: 2
IECEX LCI 11.0063X issue: 0	IECEX LCI 11.0063X issue: 1	IECEX LCI 11.0066X issue: 0
IECEX LCI 11.0066X issue: 1	IECEX LCI 11.0066X issue: 2	IECEX LCI 12.0009X issue: 0
IECEX LCI 12.0009X issue: 1	IECEX LCIE 13.0001X issue: 0	IECEX LCIE 13.0001X issue: 1
IECEX LCIE 13.0001X issue: 2	IECEX LCIE 13.0026X issue: 0	IECEX LCIE 13.0026X issue: 1
IECEX LCIE 13.0053X issue: 0	IECEX LCIE 13.0058X issue: 0	IECEX LCIE 13.0058X issue: 1
IECEX LCIE 13.0058X issue: 2	IECEX LCIE 14.0042X issue: 0	IECEX LCIE 14.0056X issue: 0
IECEX LCIE 14.0056X issue: 1	IECEX LCIE 14.0056X issue: 2	IECEX LCIE 14.0058X issue: 0
IECEX LCIE 15.0024X issue: 0	IECEX LCIE 16.0054X issue: 0	IECEX LCIE 18.0023X issue: 0
IECEX LCIE 18.0023X issue: 1	IECEX LCIE 20.0026X issue: 0	IECEX LCIE 21.0005X issue: 0
IECEX LCIE 21.0006X issue: 0	IECEX SIR 11.0018 issue: 0	IECEX SIR 11.0018 issue: 1

Comments: Production Quality Assurance Notification under directive 2014/34/EU : LCIE 03 ATEX Q 8001

2022/08/31 : addition of "op pr" (LCIE file #15791174)