



# IECEx Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **FR/LCI/QAR06.0006/18** Page 1 of 2

QAR Free Ref. No.: **19413850-791291 (TT Electronics China)** Status: **Issued**

Details of change: **surveillance audit** Date of issue: **2023-09-08**

Location(s) audited: **TT Electronics Integrated Manufacturing Services (Suzhou) Limited** Valid until: **2024-01-27**  
IMS 158-29 Hua Shan Road Feng Qiao Industrial Park  
Suzhou New District Suzhou City Jiangsu Province  
China Audit date: **2023-07-27**

Issuing ExCB: **LCIE - Laboratoire Central des Industries Electriques (LCIE)**

Manufacturer: **Meggitt SA**  
Route de Moncor 4  
1752 Villars-sur-Glâne  
Switzerland

Location of Manufacturer: **Switzerland**

Product information: Galvanic separation module  
Signal charge conditionner  
Accelerometer  
Dynamic pressure sensor  
Acceleration transducer

Type of protection: **EPL Ga : [ia], ia EPL Gb : [ib], ib, op pr EPL Gc : ec, nA, nC**

### Related QARs:

FR/LCI/QAR06.0006/00	FR/LCI/QAR06.0006/01	FR/LCI/QAR06.0006/02
FR/LCI/QAR06.0006/03	FR/LCI/QAR06.0006/04	FR/LCI/QAR06.0006/05
FR/LCI/QAR06.0006/06	FR/LCI/QAR06.0006/07	FR/LCI/QAR06.0006/08
FR/LCI/QAR06.0006/09	FR/LCI/QAR06.0006/10	FR/LCI/QAR06.0006/11
FR/LCI/QAR06.0006/12	FR/LCI/QAR06.0006/13	FR/LCI/QAR06.0006/14
FR/LCI/QAR06.0006/15	FR/LCI/QAR06.0006/16	FR/LCI/QAR06.0006/17

### Related Certificates (manual insertion)::

### Related Certificates (automatic linking)::

### Related Certificates for previous versions:

IECEx BAS 16.0030X issue: 0	IECEx BAS 16.0030X issue: 1	IECEx BAS 16.0030X issue: 2
IECEx CSAE 22.0047X issue: 0	IECEx DEK 15.0029 issue: 0	IECEx LCI 06.0007X issue: 0
IECEx LCI 06.0007X issue: 1	IECEx LCI 06.0007X issue: 2	IECEx LCI 06.0007X issue: 3
IECEx LCI 06.0008X issue: 0	IECEx LCI 06.0008X issue: 1	IECEx LCI 06.0008X issue: 2
IECEx LCI 06.0008X issue: 3	IECEx LCI 06.0009X issue: 0	IECEx LCI 06.0009X issue: 1
IECEx LCI 06.0009X issue: 2	IECEx LCI 06.0009X issue: 3	IECEx LCI 06.0010X issue: 0
IECEx LCI 06.0010X issue: 1	IECEx LCI 06.0010X issue: 2	IECEx LCI 06.0010X issue: 3
IECEx LCI 08.0041X issue: 0	IECEx LCI 08.0041X issue: 1	IECEx LCI 08.0041X issue: 2
IECEx LCI 08.0041X issue: 3	IECEx LCI 08.0041X issue: 4	IECEx LCI 10.0002X issue: 0
IECEx LCI 10.0002X issue: 1	IECEx LCI 10.0002X issue: 2	IECEx LCI 10.0002X issue: 3
IECEx LCI 10.0007X issue: 0	IECEx LCI 10.0007X issue: 1	IECEx LCI 10.0007X issue: 2
IECEx LCI 10.0007X issue: 3	IECEx LCI 10.0007X issue: 4	IECEx LCI 10.0013X issue: 0
IECEx LCI 10.0013X issue: 1	IECEx LCI 10.0013X issue: 2	IECEx LCI 10.0014X issue: 0
IECEx LCI 10.0014X issue: 1	IECEx LCI 10.0014X issue: 2	IECEx LCI 10.0015X issue: 0
IECEx LCI 10.0015X issue: 1	IECEx LCI 10.0015X issue: 2	IECEx LCI 10.0016X issue: 0
IECEx LCI 10.0016X issue: 1	IECEx LCI 10.0016X issue: 2	IECEx LCI 10.0017X issue: 0
IECEx LCI 10.0017X issue: 1	IECEx LCI 10.0017X issue: 2	IECEx LCI 10.0018X issue: 0

-- Continued on the next page



# IECEX Quality Assessment Report Summary

QAR Ref. No.: **FR/LCI/QAR06.0006/18**

Page 2 of 2

Related Certificates for  
previous versions (continued):

IECEX LCI 10.0018X issue: 1	IECEX LCI 10.0018X issue: 2	IECEX LCI 10.0019X issue: 0
IECEX LCI 10.0019X issue: 1	IECEX LCI 10.0019X issue: 2	IECEX LCI 10.0020X issue: 0
IECEX LCI 10.0020X issue: 1	IECEX LCI 10.0020X issue: 2	IECEX LCI 10.0020X issue: 3
IECEX LCI 10.0021X issue: 0	IECEX LCI 10.0021X issue: 1	IECEX LCI 10.0021X issue: 2
IECEX LCI 10.0021X issue: 3	IECEX LCI 10.0027X issue: 0	IECEX LCI 10.0027X issue: 1
IECEX LCI 10.0027X issue: 2	IECEX LCI 10.0034X issue: 0	IECEX LCI 11.0061X issue: 0
IECEX LCI 11.0061X issue: 1	IECEX LCI 11.0061X issue: 2	IECEX LCI 11.0063X issue: 0
IECEX LCI 11.0063X issue: 1	IECEX LCI 11.0066X issue: 0	IECEX LCI 11.0066X issue: 1
IECEX LCI 11.0066X issue: 2	IECEX LCI 11.0066X issue: 3	IECEX LCI 12.0009X issue: 0
IECEX LCI 12.0009X issue: 1	IECEX LCIE 13.0001X issue: 0	IECEX LCIE 13.0001X issue: 1
IECEX LCIE 13.0001X issue: 2	IECEX LCIE 13.0026X issue: 0	IECEX LCIE 13.0026X issue: 1
IECEX LCIE 13.0026X issue: 2	IECEX LCIE 13.0053X issue: 0	IECEX LCIE 13.0058X issue: 0
IECEX LCIE 13.0058X issue: 1	IECEX LCIE 13.0058X issue: 2	IECEX LCIE 14.0042X issue: 0
IECEX LCIE 14.0056X issue: 0	IECEX LCIE 14.0056X issue: 1	IECEX LCIE 14.0056X issue: 2
IECEX LCIE 14.0058X issue: 0	IECEX LCIE 15.0024X issue: 0	IECEX LCIE 16.0054X issue: 0
IECEX LCIE 18.0023X issue: 0	IECEX LCIE 18.0023X issue: 1	IECEX LCIE 20.0026X issue: 0
IECEX LCIE 21.0005X issue: 0	IECEX LCIE 21.0005X issue: 1	IECEX LCIE 21.0006X issue: 0
IECEX LCIE 21.0006X issue: 1	IECEX SIR 11.0018 issue: 0	IECEX SIR 11.0018 issue: 1

Comments: Production Quality Assurance Notification under directive 2014/34/EU : LCIE 03 ATEX Q 8001